

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

EF657 AVENUE V PUMPING STATION DEP -DDC
North 84 AVENUE V AND 11 STREET
1/2-1 BROOKLYN, NY

NY LTANKS S100879271
N/A

0.959 mi.
5061 ft.

Site 2 of 4 in cluster EF

Relative:
Higher

Actual:
14 ft.

LTANKS:

Name: AVENUE V PUMPING STATION DEP -DDC
Address: 84 AVENUE V AND 11 STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9610389 / 2003-11-18
Facility ID: 9610389
Site ID: 158704
Spill Date: 1996-11-19
Spill Cause: Tank Failure
Spill Source: Institutional, Educational, Gov., Other
Spill Class: C3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: JAKOLLEE
Referred To: Not reported
Reported to Dept: 1996-11-19
CID: 205
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: True
UST Involvement: True
Remediation Phase: 0
Date Entered In Computer: 1996-11-19
Spill Record Last Update: 2005-02-03
Spiller Name: Not reported
Spiller Company: NYC DESIGN & CONSTR.
Spiller Address: Not reported
Spiller County: 001
Spiller Contact: NYC DESIGN & CONSTRUCTIN
Spiller Phone: (212) 669-8286
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 272378
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

Remarks:

"soil test, contamination found."

All Materials:

Site ID: 158704
Operable Unit ID: 1041935
Operable Unit: 01
Material ID: 342597
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Units: G
Recovered: .00
Oxygenate: Not reported